



# SAF - LIFT

## CRANE AND HOIST OVERLOAD CUT-OFF SWITCH

(PATENT PENDING)

Prevents overloads for all  
Wire Rope Hoists up to 3/4 in. dia. rope

---

Takes only 5 in. headroom

---

Factory preset to required rope tension

---

No motion takes place until trip point is reached

---

To reset switch overload must be removed from crane hook

---

Aluminum and stainless steel components to resist rust and corrosion

---

Installed easily and quickly without disturbing hoist wire rope

---

Cuts off power to hoist "up" motion and/or gives audible or visual signal  
of attempt to lift overload



GATA Industrial Services Inc.  
P.O. Box 25056  
Cambridge, Ont. N3C 4B6  
Tel.: (519) 658-6590  
Toll: 1-888-463-1116  
Fax: (519) 658-5731